Sanitized Copy Approved for Release 2010/04/15 : CIA-RDP58-00453R000300020032-6
25 YEAR RE-REVIEW

TAB

STAT		17 Soytanber :
	٠.	· 1
		Mentrical North - Tongo J Building
, 50°2		
		It is kindly requested that the electricism install a two- way busier system between rooms 2002, 2004 and 2006 Tompo & Build- ing, in accordance with the actached dictch.
		These bustors are required for use in convection with the telephones and should be installed as soon as possible.
STAT		should be one autod for pertinant detail.